

PHOTOMETRICS BRIGHTER FW100

CRI:

CRI:	RA:
<u>CRI@3200K</u>	≥90
<u>CRI@5600K</u>	≥90

Brightness:

Lux@m:		1m	3m	5m	10m
Narrow Zoom	Warm white	66200	9710	3707	927
Wide zoom (or with frost)	Warm white	18000	2234	849	212

